


ST-15-115H module part
07647

Scully Model St 35-115-ELK, Control Monitor Explosion Proof Housing Red & Green Indicators
with Bypass Switch for Overfill protection.
07903



Scully model Optic Monitor ST-35-ELK replacement Board.
07861




Scully Model ST 47-115-EL, Control Monitor Explosion Proof Housing
Red & Green Indicators for Ground verification.
08508 **Without BYPASS**



Scully Model St 47-115-ELK, Control Monitor Explosion Proof Housing Red & Green Indicators
with Bypass Switch for grounding vehicle static grounding.
08220



Scully model Optic Monitor ST-47-ELK replacement Board.
22040



Scully Model SJ-6W optic socket (**truck side**)
07974



Scully Model SC6W Optic 30' Coiled Cable with Blue Poly WOGA Plug and Junction Box Assembly.
#08159

Scully model SC6W Optic 30" Coiled Cable & Blue Poly Plug.
21831

Scully model WOGA Blue Poly Plug Only
21766

Scully WOGA Plug Storage Hanger. "Keeps connections clean and protected."
08235

Scully model Optic Rack & Truck tester. (will work with the Civacon equipment)
08162 w/woga plug (**truck side**)

Scully model J-560 Socket Plug Only (Pull-A-Way Plug) (**rack side**)
08184

Scully Pull-a-way plug (j560) w/20' straight cable + WOGA Plug
08170

Scully Pull-a-way plug w/ coiled cable + WOGA Plug (consists of 21831 & 20469)
#

Scully 32' black coiled cable w/clamp assembly (ground Verification)
31766

Scully Universal loading rack tester (will not test truck system)
#08268

Scully 32' black coiled cable w/ plug assembly(ground verification)
#08566

Scully pilot light replacement kit, green(115V)
#08342

Scully pilot light replacement kit, red(115v)
#08343

Scully red replacement lens
#09124

Scully green replacement lens
#09125

Sculcon junction box kits w junction box, 30' coiled cable or 20' straight cable,
and blue plug(Optic) or green plug(Thermistor 2 wire optic)